

POUTRELLES

Profils	Pds	Longueur stockée
IPE 80	6,2	6-12-15
IPE 100	8,3	6-12-15
IPE 120	10,7	6-12-15
IPE 140	13,3	6-12-15
IPE 160	16,3	6-12-15
IPE 180	19,4	6-12-15
IPE 200	23,1	10-11-12-13-14-15-16
IPE 220	26,7	10-11-12-13-14-15-16
IPE 240	31,6	10-11-12-13-14-15-16
IPE 270	37,2	10-11-12-13-14-15-16
IPE 300	43,5	10-11-12-13-14-15-16
IPE 330	50,6	10-11-12-13-14-15-16
IPE 360	58,8	10-11-12-13-14-15-16
IPE 400	68,3	12-13-14-15
IPE 450	80,0	12-13-14-15
IPE 500	93,4	12-13-14-15
IPE 550	109	12-13-14-15
HEA 100	17,2	6-12-15
HEA 120	20,5	6-12-15
HEA 140	25,4	6-12-15
HEA 160	31,3	6-12-15
HEA 180	36,6	6-12-15
HEA 200	43,6	6-12-15
HEA 220	52,0	6-12-15
HEA 240	62,1	6-12-15
HEA 260	70,3	6-12-15
HEA 280	78,7	6-12-15
HEA 300	91,0	6-12-15
HEA 450	144,0	6-12-15
HEB 100	21,0	6-12-15
HEB 120	27,5	6-12-15
HEB 140	34,7	6-12-15
HEB 160	43,9	6-12-15
HEB 180	52,7	6-12-15
HEB 200	63,1	6-12-15
HEB 220	73,6	6-12-15
HEB 240	85,7	6-12-15
HEB 260	95,8	6-12-15
HEB 280	106,1	6-12-15
HEB 300	120,5	6-12-15
HEB 320	130,8	6-12-15
HEB 340	138	6-12-15
HEB 360	146	6-12-15